


Legend

| | | |
|------------------|-----------|------------------|
| Poor Coverage | Highway | Water Body |
| Useable Coverage | Pri. Road | Trunking Systems |
| Good Coverage | Sec. Road | |



DISCLAIMER: This survey is representative of the anticipated coverage from the Transmitter Site. Actual coverage may vary due to terrain, foliage, weather, interference and other factors. Even if an area is shaded, indicating coverage, it does not necessarily mean that there is complete radio coverage, in fact, there are numerous "no coverage" areas (including areas too small to depict) within the shaded areas. Wireless service is a radio technology that is subject to transmission limitations caused by service area limitations, customer equipment or its installation and other like conditions. In addition, service may be limited or suspended due to system capacity limitations or system repairs or modifications.

Repeater Network Valhalla Mobile Coverage

Produced by:
Goosetown Communications GIS
March 2005

Copyright 2005 - No claim to original works

Source: US Census / ComStudy /
Goosetown GIS